

תְּשִׁבְעָה
תְּשִׁבְעָה
תְּשִׁבְעָה
תְּשִׁבְעָה
תְּשִׁבְעָה
תְּשִׁבְעָה
תְּשִׁבְעָה

10641 HWY 36, COVINGTON, GA 30014 t 770.786.3031 f 770.786.3046

Lendmark Financial Services (Level 1)

Dear Sirs: Success
Covington, Ga

This architectural floor plan illustrates a building section with the following key features:

- MAIN BREAK ROOM:** A large rectangular room labeled "MAIN BREAK ROOM" with a circled "18" indicating its area or capacity. It is located on the left side of the main corridor.
- Service Area:** A long, narrow room located at the bottom of the plan, featuring a large rectangular opening in the center.
- Corridors:** A central vertical corridor and a horizontal corridor connecting the main rooms.
- Doors:** Small rectangular symbols representing doors, located at the intersections of the corridor paths.
- Vertical Lines:** Two vertical lines on the far left and right edges of the plan.

MAIN BREAK ROOM DEMOLITION N

- D1 REMOVE EXISTING FLOORING AND RUBBER BASE.
- D2 REMOVE EXISTING WALL AND BASE CABINETS.
- D3 REMOVE EXISTING ACOUSTICAL CEILING TILE.
GRID TO REMAIN IN PLACE.
- D4 REMOVE EXISTING LAMPS FROM ALL LIGHT FIXTURES

Enlarged Demolition Plan - Main Break Room

SCALE: 1/4" :

This architectural floor plan shows a vertical cross-section of a building. The main structure is a rectangular room with a vertical wall on the left and a vertical support column on the right. A horizontal beam connects the top of the vertical wall to the top of the support column. A curved line extends from the top of the support column to the right, representing an external wall or a corner. In the center of the room, the text 'HR BREAK ROOM' is written in a large, bold, sans-serif font, with '(67)' in a circle positioned below it. At the bottom of the room, there is a horizontal line with a rectangular cutout in the center, representing a door or entrance. A dashed horizontal line extends from the bottom of the room towards the left, indicating a continuation of the floor or a shared wall with an adjacent room.

HR BREAK ROOM DEMOLITION NOTES:

- D1 REMOVE EXISTING FLOORING AND RUBBER BASE.
- D2 REMOVE EXISTING WALL AND BASE CABINETS.
- D3 REMOVE EXISTING ACOUSTICAL CEILING TILE.
GRID TO REMAIN IN PLACE.
- D4 REMOVE EXISTING LAMPS FROM ALL LIGHT FIXTURES.

Enlarged Demolition Plan - HR Break Room

SCALE: 1/4" = 1'-0"

FRONT
CONFERENCE
ROOM

32

FRONT CONFERENCE ROOM DEMOLITION NOTE

- D1 REMOVE EXISTING FLOORING. WOOD BASE TO REMAIN.
- D2 REMOVE CHAIR RAIL. PATCH WALL AS REQUIRED.
- D3 REMOVE EXISTING LAMPS FROM ALL LIGHT FIXTURES.
- D4 REMOVE EXISTING WINDOW BLINDS.
- D5 REMOVE EXISTING PROJECTION SCREEN AND WOOD CASE FROM REAR WALL. PATCH WALL AS REQUIRED.
(HOLD THESE ITEMS FOR OWNER.)
- D6 REMOVE EXISTING ACOUSTICAL CEILING TILE.
GRID TO REMAIN IN PLACE.

Enlarged Demolition Plan - Front Conference Room

SUPPORT
SERVICES
BREAK

97

SUPPORT SERVICES BREAK ROOM DEMOLITION NOTES:

- D1 REMOVE EXISTING WALL AND BASE CABINETS.
- D2 REMOVE EXISTING ACOUSTICAL CEILING TILE.
GRID TO REMAIN IN PLACE.
- D3 REMOVE EXISTING LAMPS FROM ALL LIGHT FIXTURES.

Enlarged Demolition Plan – Support Services Break Room

SCALE: 1/4" = 1'-0"

WINGS AND SPECIFICATIONS ARE
INSTRUMENTS OF SERVICE AND
SHALL REMAIN THE PROPERTY OF
THE CORPORATION WHETHER THE
PROJECT FOR WHICH THEY ARE MADE
IS EXECUTED OR NOT. THEY ARE NOT
TO BE USED ON OTHER PROJECTS
OR EXTENSIONS TO THIS PROJECT
UNLESS AGREED BY AGREEMENT IN WRITING
TO APPROPRIATE COMPENSATION
TO THIS CORPORATION.

DRAWING NUMBER
A-1.2
3 of *